


Audiotonix

Steam
powered mixer

Assembly Instructions



Contents


Introduction	3
• Important Safety Warnings	3
• Advice for Teachers	4
• Soldering Tips	5
• Soldering General Advice and Precautions	6
• Good vs. Bad Solder Joints	7
• Before You Begin	8
o Tools Required	8
o What's in the Box?	9
Line In PCB Assembly	10
• Components	11
• Line In PCB Bare Board	12
• Line In PCB Circuit Diagram	13
• Assembly	14
Master Out PCB Assembly	36
• Components	37
• Bare Board	39
• Circuit Diagram	40
• Assembly	41
Mechanical Assembly	72
• Components	73
• Assembly	74
Operation of Unit (How to Use Your Finished Mixer)	85
• Rear Panel Diagram and Explanation	86
• Front Panel Diagram	87
• Front Panel Diagram Explanation	88
System Block Diagram	90
Further Research	91

Introduction



Important Safety Warnings

- **Warning:** Read and follow all warnings and instructions to avoid risk of serious injury or death.
- **Warning:** Do not allow children under the age of 12 to play with, use, or attempt to assemble this product. Children over the age of 12 should be supervised by a responsible adult during the assembly of this product.
- **Warning:** Check to make sure the product is correctly assembled before use. An incorrectly assembled product may pose the risk of electric shock, fire, overheating, or explosion.
- **Warning:** Ensure you have consulted relevant training information for how to assemble kit electronics. This guide should only be used to supplement formal educational material. If you are unsure of any element or step, seek the help of an individual who is qualified as an instructor or a trained service technician.
- **Warning:** Do not put your fingers in the component envelopes! The component legs have sharp points and can get caught between your finger and your nail!



- **Warning:** Eyes protection must be used when soldering due to fumes and risk of solder splatter.
- **Warning:** Ensure all soldering assembly is done in a well ventilated area.
- **Warning:** Soldering irons get very hot. **Do not touch the metal part.** Handle with care. Follow original manufacturers instructions closely and use appropriate protective equipment.
- **Warning:** Some metal components may have sharp edges. Handle with care.

STEAM powered mixer

- **Warning:** Handle mechanical tools with caution. Ensure that all screw drivers are the correct sizes for the screws. Slipping with a spanner, screwdriver or any other tool, can cause severe injury and damage to components or circuits.
- **Warning:** Incorrect assembly of some components might cause them to explode or fail.
- **Warning:** Electrical shorts might cause components to malfunction and break or overheat. Check all joints for shorts and confirm component orientations are correct before attempting to power the unit.
- **Warning:** Turning on or attempting to power the unit during the assembly process can lead to damage to component as well as physical harm to the user.
- **Caution:** This kit contains delicate electronic circuits and components which can be broken easily. Please handle with care and take appropriate steps to avoid damage.

Advice for Teachers

Before proceeding with this project in an educational setting there is a video which should be watched before the first session. This video gives some examples of the equipment required, as well as some general advice on how to proceed safely and efficiently through the assembly process.

Instructions
for teachers



Soldering Tips

Soldering Step-by-Step

These are some steps which act as a rough guide to solder the components.

1. Check to see if there is a required orientation for the component
2. Load the component into the holes
3. Make sure the component is sitting flat
4. Clean and tin the tip of the soldering iron
5. Position the flat edge of the tip of the soldering iron against the board and component leg for 3 - 5 seconds
6. Hold a length of solder and manoeuvre it so that the end taps the point where the component and the solder pad meet. Be careful not to use too much solder
7. Inspect the joint to make sure there is a good connection and the correct amount of solder has been used

All components should be soldered on the same side of the board, with the exception of one LED which will be soldered on the opposite side of one board only. The silk-screening (white printed ink) on the PCB is used to identify the location of each component - if there is no silk-screening then this means that the board is upside down.

Soldering Tutorial Videos

There is a QR code for each step which links to a video showing how the component is soldered. These videos are identified by the icons below - this QR code links to a video on how to solder.



How to solder



Additional Soldering Advice

For a more in depth introduction to soldering, this YouTube video provides a detailed guide to soldering

[How to Solder \(Beginner's Guide\)](https://www.youtube.com/watch?v=3jAw4ILRBxU)
<https://www.youtube.com/watch?v=3jAw4ILRBxU>




Soldering General Advice and Precautions

These are some things to watch out for.


- Soldering should be done on a solid, level surface and the soldering iron should never be put into contact with flammable materials.
- Solder components in a well-ventilated area and avoid inhalation of soldering smoke/fumes.
- Ground planes take longer to heat up - these are identifiable by the fact they are surrounded by copper (other pads often have a single track leading up to them). These might take 5 seconds or so to heat up.
- Some components have orientations - **soldering these in the wrong way round could cause the component to break or explode!**
- Some components are sensitive to too much heat. This is true for the ICs (Integrated Circuits - black rectangles with lots of legs). These styles of component should not normally take more than 5 seconds for the solder to join to both the component and the pad. Allow time for component to cool down between legs.

Good vs. Bad Solder Joints


Good Joint Example



Bad Joint Example 1



Bad Joint Example 2



Before you begin

Tools Required

Electronic Assembly:

- Eye protection
- Appropriate clothing - e.g. lab coats
- Soldering iron
- Solder - **Lead free solder must be used**
- Flux
- Wire Cutters



Mechanical Assembly:

- # 0 Pozidriv® Screw Driver
- # 1 Pozidriv® Screw Driver
- 10 mm Spanner

Power and Cables Required for Operation of Finished Unit

- | | |
|--|-----|
| • 3.5 mm to 3.5 mm Auxillary Cable | x 2 |
| • USB A - USB B Cable | x 1 |
| • Recommended PSU USB 2.0, 5V 0.5A max | x 1 |

What's in the box?

Mechanical Components:

• Chassis Top	x 1
• Chassis Bottom	x 1
• VU Bracket	x 1
• Clear Acrylic Sides	x 2
• Fader Cap	x 1
• Rotary Knobs	x 7
• Rubber O-Ring	x 7
• Rectangular Push-Switch Caps	x 4
• M2 Countersink Screws	x 2
• M3 Button Head Screws	x 27
• Adhesive Foot	x 4
• Plastic Grommet	x 1

Wiring Looms:


• VU Meter Loom	x 2
• Fader Loom	x 1
• Ribbon Cable Loom	x 1

Electronic Components:

• Line In PCB	x 2
• Master Out PCB	x 1
• Line In Components Box	x 2
• Master Out Components Box	x 1

Line In PCB

Solder Assembly Guide




Line In PCB Components

Issue A Bare PCB


- 1 Resistor 330R 1/4W
- 2 Resistor 1K 1/4W
- 3 Resistor 1K2 1/4W
- 4 Resistor 3K6 1/4W
- 5 Resistor 4K7 1/4W
- 6 Resistor 10K 1/4W
- 7 Resistor 15K 1/4W
- 8 Resistor 22K 1/4W
- 9 Resistor 47K 1/4W
- 10 Op-Amp
- 11 Capacitor Ceramic 47pF 100V 5%
- 12 Capacitor Polyester 47nF 100V
- 13 Capacitor Polyester 100nF 63V
- 14 3.5mm Stereo Audio Jack Connector
- 15 10 Way Right-Angle IDC Header
- 16 Switch Horizontal Push Latched 4-Pole
- 17 Pot. Rotary 10K Lin +/-20%
- 18 Pot. Rotary 10K Log +/-20%
- 19 Pot. Rotary 100K Lin +/-20%
- 20 Capacitor Electrolytic 22uF 20% 50V
- 21 Green LED

Line In PCB Bare Board

- Thick white lines shows the channel signal
- Dotted white lines show control signals
- Dotted boxes identify different processing sections.



Line In PCB Circuit Diagram



Line In PCB Solder Assembly

1

Resistor 330R 1/4W

R1, R2

1 STEAM

Line In
330R x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

2

Resistor 1K 1/4W

R3

2 TEAM

Line In
1K x1



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

3

Resistor 1K2 1/4W

R22, R24, R26, R28

3 ∫TEAM

Line In
1K2 x4



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

4

Resistor 3K6 1/4W

R14, R18

4 TEAM

Line In
3K6 x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

5

Resistor 4K7 1/4W

R10, R16

5 STEAM

Line In
4K7 x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

6

Resistor 10K 1/4W

R4, R5, R6, R7, R8, R9, R12, R15, R23, R25

6 TEAM

Line In
10K x10



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

7

Resistor 15K 1/4W

R13, R19, R20, R29

7 STEAM

Line In
15K x4



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

8

Resistor 22K 1/4W

R21, R27

8 team

Line In
22K x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly

9

Resistor 47K 1/4W

R11, R17

9 STEAM

Line In
47K x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Line In PCB Solder Assembly

10

Op-Amp (Operational Amplifier)

U1, U2, U3

10 TEAM
Line In
Op-Amp x3



Check Part Orientation!



How to solder
an Op-Amp



Soldering Tips:


1. Place component so that it is flat against board. **Check part orientation is correct!**
2. Solder one of the corner legs
3. Check that component is still flat then solder the leg diagonally opposite
4. Again check the component is flat. If not, press the iron against the end of the problematic leg until the solder melts and using a finger, push the component flat from the other side of the board
5. Solder the remaining legs

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**

Warning! If these are fitted the wrong way round, they might explode when the unit is powered.

Warning! These components can get hot very quickly which can cause a risk of burning.

Caution! Do not apply heat from the iron for more than 5 seconds at a time, as this might damage the component.



Line In PCB Solder Assembly

11

Capacitor Ceramic 47pF

C4, C5, C6, C7, C11, C18

11 STEAM

Line In
47pF x6



Orientation Not Critical



How to solder
a ceramic
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly


12

Capacitor Polyester 47nF

C9, C10, C20, C23

12 TEAM

Line In
47nF x4



Orientation Not Critical



How to solder
a polyester
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly


13

Capacitor Polyester 100nF

C3, C8, C14, C15, C21, C22

13 STEAM

Line In
100nF x6



Orientation Not Critical



How to solder
a polyester
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Line In PCB Solder Assembly



14

3.5mm Stereo Audio Jack Connector

J1

14 TEAM

Line In
J1 x1



How to solder
a 3.5 mm Audio
Jack Connector



Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.

Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**



Line In PCB Solder Assembly


15

10 Way Right-Angle IDC Header

J2

15 STEAM

Line In
J2 x1



Check Part Orientation!



How to solder
a 10 Way IDC
Header




Soldering Tips:

Make sure component is flat before soldering. This part easily rocks out of position.

It might help to try resting this component on top of something to make sure it stays in position when soldering.

Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**




Line In PCB Solder Assembly

16

Switch Horizontal Push Latched
4 Pole
SW1

16 TEAM
Line In
SW1 x1



Check Part Orientation!



How to solder
a horizontal
push switch



Soldering Tips:


Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.

Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.

Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**




Line In PCB Solder Assembly

17

Pot. Rotary 10K Lin +/-20% - B103

VR1

17 steam
Line In
VR1 x1



Check Part Orientation!



How to solder
a rotary
potentiometer



Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.


Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**




Line In PCB Solder Assembly

18

Pot. Rotary 10K Log +/-20% - A103

VR3

18 $\int_{\text{TEAM}}$
Line In
VR3 x1



Check Part Orientation!



How to solder
a rotary
potentiometer



Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.


Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**




Line In PCB Solder Assembly

19

Pot. Rotary 100K Lin +/-20% - C104 Dual Gang

VR2

19 steam
Line In
VR2 x1



Check Part Orientation!



How to solder
a rotary
potentiometer



Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.


Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**




Line In PCB Solder Assembly

20

Capacitor Electrolytic 22uF 20% 50V

C1, C2, C12, C13, C16, C17, C19,
C24, C25, C26



Check Part Orientation!



How to solder
an electrolytic
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go.
Check the part orientation! The pale line printed on the capacitor identifies the **negative** pin.
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Warning! If these are fitted the wrong way round, they could explode when the unit is powered.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Line In PCB Solder Assembly

21

Green LED

DI



Check Part Orientation!



How to solder
an LED



Soldering Tips:


1. Decide which side of the board this part needs to go on (there are two Line In PCBs, one has the LED fitted on one side, and the other one has it fitted on the opposite side).
Check which side this one needs to be fitted.
2. Pull component through the board as far as it can go.
Check the part orientation! If this is incorrect, the LED will not light up.
2. Put a 45 degree bend in each leg to hold the component in position, check the component is still flat.
3. Solder the component.
4. Using wire cutters, trim the leg to roughly 1 mm long.

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Line In PCB Solder Assembly

Board Complete

Master Out PCB

Solder Assembly



Master Out PCB Components

Issue A Bare PCB

- ① Resistor 47R 1/4W
- ② Resistor 2K4 1/4W
- ③ Resistor 3K6 1/4W
- ④ Resistor 4K7 1/4W
- ⑤ Resistor 5K6 1/4W
- ⑥ Resistor 6K8 1/4W
- ⑦ Resistor 7K5 1/4W
- ⑧ Resistor 10K 1/4W
- ⑨ Resistor 15K 1/4W
- ⑩ Resistor 47K 1/4W
- ⑪ Capacitor Ceramic 47pF 100V 5%
- ⑫ Capacitor Electrolytic 22uF 20% 50V
- ⑬ Capacitor Polyester 100nF 63V
- ⑭ Capacitor Polyester 2700pF 100V
- ⑮ Capacitor Electrolytic 4.7uF 16V
- ⑯ Axial Inductor 6.8uH
- ⑰ Diode 1N5711 70V 15mA
- ⑱ Op-Amp
- ⑲ IC Switch SPDT
- ⑳ Isolated Module DC-DC Converter
- ㉑ 3.5mm Stereo Audio Jack Connector
- ㉒ 10 Way Right-Angle IDC Header
- ㉓ Connector 4 Way USB 2.0 type B R/A
- ㉔ Header SIL 2 Way Friction Lock 0.156"
- ㉕ Header SIL 6 Way Friction Lock 0.1"

continued overleaf


steam powered mixer

Master Out PCB components continued

- ②6 Pot. Rotary 10K Lin +/-20%
- ②7 Switch Horizontal Push Latched 2Pole
- ②8 Metal Joint Block M9000
- ②9 Capacitor Ceramic Disc 470 pF 3 kV
- ③0 Axial Fuse 125V 1 A


Master Out PCB Bare Board

- Thin white lines show input channel signals
- Thick white lines shows the master channel signal
- Dotted white lines show control signals
- Dotted boxes identify different processing sections.



STEAM powered mixer

Master Out PCB Circuit Diagram



Master Out PCB Solder Assembly

1 Resistor 47R 1/4W R2, R4, R17, R18



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

2

Resistor 2K4 1/4W

R19, R23, R37, R40

2 STEAM
Master
2K4 x4



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

3

Resistor 3K6 1/4W

R11, R14

3 TEAM

Master
3K6 x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

4

Resistor 4K7 1/4W

R1, R3, R6, R9, R12, R16

4 STEAM
Master
4K7 x6



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

5

Resistor 5K6 1/4W

R28, R34

5 team

Master
5K6 x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

6

Resistor 6K8 1/4W

R27, R33

6 STEAM
Master
6K8 x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly


7

Resistor 7K5 1/4W

R20, R21, R24, R32, R38, R42



Orientation Not Critical



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions. **Make sure you are wearing eye protection.**



Master Out PCB Solder Assembly

8

Resistor 10K 1/4W

R8, R10

8 STEAM
Master
10K x2



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

9

Resistor 15K 1/4W

R13, R15, R35, R36, R43, R46

9 TEAM

Master
15K x6



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

10

Resistor 47K 1/4W

R5, R7, R22, R25, R26, R29, R30, R31,
R39, R41, R44, R45, R47

10 TEAM
Master
47K x13



Orientation Not Critical



How to solder
a resistor



Soldering Tips:

1. Pull component through the board
2. Using pliers if necessary, pull the component flat against the board
3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
4. Solder the component
5. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

11

Capacitor Ceramic 47pF
100V 5%

C9, C11, C14, C21, C22, C32, C33,
C36, C38, C44

11 TEAM

Master
47pF x10



Orientation Not Critical



How to solder
a ceramic
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

12

Capacitor Electrolytic 22uF
20% 50V

C4, C5, C12, C13, C15, C16, C19, C20,
C25, C28, C30, C31, C39, C40, C42, C45

12 steam
Master
22uF x16



Check Part Orientation!



How to solder
an electrolytic
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go.
Check the part orientation! The pale line printed on the capacitor identifies the **negative** pin.
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Warning! If these are fitted the wrong way round, they could explode when the unit is powered.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

13

Capacitor Polyester 100nF
63V

C8, C10, C17, C18, C24, C26, C27,
C29, C34, C37, C41, C43

13 TEAM
Master
100nF x12



Orientation Not Critical



How to solder
a polyester
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

14

Capacitor Polyester 2.7nF
100V
C23, C35

14 steam
Master
2.7nF x2



Orientation Not Critical



How to solder
a polyester
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

15

Capacitor Electrolytic 4.7uF
16V

C1, C2, C6, C7

15 TEAM
Master
4.7uF x4



Check Part Orientation!



How to solder
an electrolytic
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go.
Check the part orientation! The pale line printed on the capacitor identifies the **negative** pin.
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Warning! If these are fitted the wrong way round, they could explode when the unit is powered.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

16

Axial Inductor 6.8uH
LI

16 steam
Master
6.8uH x1



Orientation Not Critical



How to solder
an axial
inductor



Soldering Tips:


1. Pull component through the board
 2. Using pliers if necessary, pull the component flat against the board
 3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
 4. Solder the component
 5. Using wire cutters, trim the leg to roughly 1 mm long
- Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

17

Diode 70V 15mA

D1, D2, D3, D4, D5, D6, D7, D8

17 TEAM
Master
DIODE x8



Check Part Orientation!



How to solder
a diode



Soldering Tips:


1. Pull component through the board as far as it can go.
Check the part orientation! If this is incorrect, the VU Meters will not work as intended
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly


18

Op-Amp (Operational Amplifier)

U2, U3, U4, U6, U7

18 STEAM

Master
Op-Amp x5



Check Part Orientation!



How to solder
an Op-Amp



Soldering Tips:


1. Place component so that it is flat against board. **Check part orientation is correct!**
2. Solder one of the corner legs
3. Check that component is still flat then solder the leg diagonally opposite
4. Again check the component is flat. If not, press the iron against the end of the problematic leg until the solder melts and using a finger, push the component flat from the other side of the board
5. Solder the remaining legs

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**

Warning! If these are fitted the wrong way round, they could explode when the unit is powered.

Warning! These components can get hot very quickly which can cause a risk of burning.

Caution! Do not apply heat from the iron for more than 5 seconds at a time, as this might damage the component.




Master Out PCB Solder Assembly

19


IC Switch SPDT 240R
U5

19 TEAM

Master
U5 x1



Check Part Orientation!



How to solder
an IC switch



Soldering Tips:

1. Place component so that it is flat against board. **Check part orientation is correct!** It is very easy to accidentally solder this part the wrong way around - there are notches at either end. **The deep, semi-circular recess identifies the correct orientation.** Not the shallow circular recess at the opposite end
2. Solder one of the corner legs
3. Check that component is still flat then solder the leg diagonally opposite
4. Again check the component is flat. If not, press the iron against the end of the problematic leg until the solder melts and using a finger, push the component flat from the other side of the board
5. Solder the remaining legs




Warning! While soldering, there is a risk of solder splatter.

Make sure you are wearing eye protection.

Warning! If these are fitted the wrong way round, they could explode when the unit is powered.


Warning! These components can get hot very quickly which can cause a risk of burning.

Caution! Do not apply heat from the iron for more than 5 seconds at a time, as this might damage the component.



Master Out PCB Solder Assembly

20 Isolated Module DC-DC Converter U1



How to solder
a DC-DC
converter




Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

21

3.5mm Stereo Audio Jack Connector

J1, J7

21 TEAM
Master
J1/J7 x2



How to solder
a 3.5 mm Audio
Jack Connector




Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter. Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

22

10 Way Right-Angle IDC Header

J6

22 steam
Master
J6 x1



Check Part Orientation!



How to solder
a 10 Way IDC
Header




Soldering Tips:

Make sure component is flat before soldering. This part easily rocks out of position.

It might help to try resting this component on top of something to make sure it stays in position when soldering

Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**



Master Out PCB Solder Assembly


23

Connector 4 Way USB 2.0
type B R/A

J2

23 TEAM

Master
J2 x1



How to solder
a USB
connector




Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork
More heat (time) and slightly more solder is required for the outside two legs of this component.

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

24


Header SIL 2 Way Friction
Lock 0.156"

J3, J4

24 steam
Master
J3/J4 x2



Check Part Orientation!



How to solder
a 2 way header




Soldering Tips:

1. Pull component through the board as far as it can go.
Check the part orientation! If this is incorrect, the product will not work and multiple components will fail
2. Solder the component.

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

25

Header SIL 6 Way Friction
Lock 0.1"

J5

25 TEAM
Master
J5 x1



Check Part Orientation!



How to solder
a 6 way header




Soldering Tips:

1. Pull component through the board as far as it can go.
Check the part orientation! If this is incorrect, the product will not work and multiple components will fail
2. Solder the component.

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

26

Pot. Rotary 10K Log +/-20%
VR1

26 steam
Master
VR1 x1



Check Part Orientation!



How to solder
a rotary
potentiometer



Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.


Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.



Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

27

Switch Horizontal Push
Latched 2-Pole
SW1, SW2

27 TEAM
Master
SW1/2 x2



Check Part Orientation!



How to solder
a horizontal
push switch



Soldering Tips:


Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork.

Solder one pin and then solder the opposite corner. Make sure component is still flat. If not, reheat the pin and push the component flat.

Note: It is difficult to remove this component once more than one pin has been soldered so it is worth checking to make sure it is still flat after soldering the first two pins.

Warning! These components can get hot very quickly which can cause a risk of burning.

Warning! While soldering, there is a risk of solder splatter. **Make sure you are wearing eye protection.**



Master Out PCB Solder Assembly


28

Metal Joint Block

MTGI

28 steam

Master
MTG x1



Check Part Orientation!



How to solder
a metal joint
block




Soldering Tips:

Make sure component is flat before soldering first pin, if this is soldered badly, it won't align with the metalwork
More heat (time) and slightly more solder is required for this component - **this means it gets hotter than other components.**

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

29

Capacitor Ceramic Disc 470
pF 3 kV

C3

29 TEAM
Master
470pF x1



Orientation Not Critical



How to solder
a high voltage
capacitor



Soldering Tips:

1. Pull component through the board as far as it can go
2. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
3. Solder the component
4. Using wire cutters, trim the leg to roughly 1 mm long


Note: Orientation is not important for these parts - but it is for some capacitors!

Warning! These components can get hot very quickly which can cause a risk of burning.




Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.



Master Out PCB Solder Assembly

30 Axial Fuse 125V 1 A
FI



Orientation Not Critical



How to solder
an axial fuse



Soldering Tips:


1. Pull component through the board
 2. Using pliers if necessary, pull the component flat against the board
 3. Put a 45 degree bend in each leg to hold the component in position while making sure that the component is still flat
 4. Solder the component
 5. Using wire cutters, trim the leg to roughly 1 mm long
- Note: Orientation is not important for these parts, although for some people, convention is that the gold band is on the right or top

Warning! These components can get hot very quickly which can cause a risk of burning.



Warning! While soldering, there is a risk of solder splatter.
Make sure you are wearing eye protection.

Warning! When trimming the component legs with cutters, shards of metal and wire can fire off in unpredictable directions.
Make sure you are wearing eye protection.




Master Out PCB Solder Assembly

Board Complete

Mechanical Assembly

Metalwork Assembly



Mechanical Assembly Components

Mechanical Components:

• Chassis Top	x 1
• Chassis Bottom	x 1
• VU Bracket	x 1
• Clear Acrylic Sides	x 2
• Fader Cap	x 1
• Rotary Knobs	x 7
• Rubber O-Ring	x 7
• Rectangular Push-Switch Caps	x 4
• M2 Countersink Screws	x 2
• M3 Button Head Screws	x 27
• Adhesive Foot	x 4
• Plastic Grommet	x 1

Wiring Looms:

• VU Meter Loom	x 2
• Fader Loom	x 1
• Ribbon Cable Loom	x 1

Mechanical Assembly

1


VU Meters

Components Required:

- | | |
|-------------------------|-----|
| • Chassis Top | x 1 |
| • VU Bracket | x 1 |
| • M3 Button Head Screws | x 6 |
| • VU Meter Loom | x 2 |

Tools Required :

- # 1 Pozidriv® Screw Driver



Mechanical Assembly

2


Fader Loom

Components Required:

- Fader Loom x 1
- M2 Countersink Screws x 2

Tools Required :

- # 0 Pozidriv® Screw Driver



Mechanical Assembly

3

Line In PCB

Components Required:


- Potentiometer Nut x 7
- Potentiometer Washer x 7
- Rubber O-Ring x 7

Tools Required :

- 10 mm Spanner

Assembly Notes:

- Fit the Washer, Nut and then Rubber O-ring. Make sure the O-Ring is sitting in the middle of the smooth section of the potentiometer shaft.



Mechanical Assembly

4


Master Out PCB

Components Required:

- | | |
|-------------------------|-----|
| • Potentiometer Nut | x 1 |
| • Potentiometer Washer | x 1 |
| • Rubber O-Ring | x 1 |
| • M3 Button Head Screws | x 1 |

Tools Required :

- 10 mm Spanner
- # 1 Pozidriv® Screw Driver



Assembly Notes:

- Remove the knurled nut from the 3.5 mm jack located at the Cue/Phones position and re-fit and hand-tighten once the other fixings are fitted
- Fit the Washer, Nut and then Rubber O-ring. Make sure the O-Ring is sitting on the smooth section of the potentiometer shaft.

Mechanical Assembly

5

Second Line In PCB

Components Required:


- Potentiometer Nut x 7
- Potentiometer Washer x 7
- Rubber O-Ring x 7

Tools Required :

- 10 mm Spanner

Assembly Notes:

- Fit the Washer, Nut and then Rubber O-ring. Make sure the O-Ring is sitting in the middle of the smooth section of the potentiometer shaft.



Mechanical Assembly

6


Loom Assembly

Components Required:

- Ribbon Cable Loom x 1

Assembly Notes:


- Connect all looms (VU Meters x2, Fader Loom, and Ribbon Cable)
- Make sure that the VU Meters are connected the correct way around - this is labelled on the PCB!



Mechanical Assembly

7

Chassis Base



Components Required:

- M3 Button Head Screws x 4
- Plastic Grommet x 1
- Chassis Bottom x 1

Tools Required :

- # 1 PoziDriv® Screw Driver

Assembly Notes:

- Push-fit Plastic Grommet so that it snaps into place - check the orientation is correct
- Remove the knurled nut from the 3.5 mm jacks on both line in PCBs and the master ut PCBs and re-fit and hand-tighten once the Chassis Bottom is fitted

Mechanical Assembly

8

Clear Sides

Components Required:


- Clear Acrylic Sides x 2
- M3 Button Head Screws x 16

Tools Required :

- # 1 Pozidriv® Screw Driver

Assembly Notes:

- Ensure the orientation of the Clear Acrylic Sides is correct. There is a notch in one corner which clears the step in the metalwork




Mechanical Assembly

9

Knobs and Switch Caps

Components Required:

- | | |
|--------------------------------|-----|
| • Fader Cap | x 1 |
| • Rotary Knobs | x 7 |
| • Rectangular Push-Switch Caps | x 4 |



Assembly Notes:

- Make sure all pots are rotated to the left, so alignment of line on the rotary knob can be aligned correctly

Mechanical Assembly

10

Adhesive Feet


Components Required:

- Adhesive Foot

x 4


Assembly Notes:

- Use a ruler to position feet roughly 10 mm from the outside of the assembled unit to the edge of the foot



Mechanical Assembly

Mechanical Assembly Complete



Operation of Unit


How to Use Your Finished Mixer

- **Warning!** Check to make sure the product is correctly assembled before use. An incorrectly assembled product may pose the risk of electric shock, fire, overheating or explosion.



Operation of Unit

Rear Panel Diagram and Explanation



1

USB B Power input. 5V 500 mA. **Warning:** This must be provided from a rated and certified supply. Using an unrated supply could result in fire, risk of serious injury or death.



2

Channel 1 Line Input. The unit is designed for consumer rated electronic outputs, for example laptops, audio players, mobile phones. (Rated to -10 dBV). Connector socket is a 3.5 mm jack.

3


Channel 2 Line Input. The unit is designed for consumer rated electronic outputs, for example laptops, audio players, mobile phones. (Rated to -10 dBV). Connector socket is a 3.5 mm jack.

13

Master Line Output. The output is designed for powered/active speakers.. Connector socket is a 3.5 mm jack.

Operation of Unit

Front Panel Diagram



Operation of Unit

Front Panel Diagram Explanation

- 2** Graphical representation of Channel 1 Line Input. This indicates the beginning of the signal path within the mixer
- 3** High Pass Filter. This knob attenuates (removes) lower frequencies. It is used as an effect to create a sense of drama and to ensure that the bass frequencies of both tracks are not clashing (clashing bass frequencies are very noticable, whereas higher frequencies tend to blend together more nicely)
- 4** Headphone Cue Switch. Press this switch to listen to this channel in your headphones. **Warning:** If the Cue/Phones level is too loud, pressing this switch could damage your hearing! Check that the Cue/Phones is at a reasonable level for your headphones. **Note:** If the cue button does not appear to be working on the channels, it could be that the master switch is activated (see item 8) 
- 5** Channel 1 Output Level. Use this knob to control the output level of Channel 1. This will control how much signal is sent to the master bus (bus is a word used in audio which normally refers to a channel which sums its inputs and routes them to a mono or stereo output)
- 6** Left/Right Balance. Use this knob to direct how much signal is sent to the left and right master stereo outputs. This is also known as panning
- 7** Boost Button. This button takes advantage of a psycho-acoustic effect to make the sound of the track sound bigger/fatter. It boosts the low and high frequencies while lowering the mids. Use with caution - if your channel level is already high, the signal will clip
- 8** Cue Master Button. This button is useful as it allows you to hear your master mix without having speakers plugged in. **Note:** This switch will bypass Cue for Channel 1 and Channel 2, if it is pressed, it will always solo/cue the master channel, **regardless of whether or not the other two switches are pressed.**

Operation of Unit

9

Cue/Phones Level and Output. This knob controls the output level for the headphones **Warning:** If the Cue/Phones level is too loud this **will** damage your hearing! Check that the Cue/Phones is at a reasonable level for your headphones. Take a break after listening for an extending period of time. Ears are very sensitive to sound. If you want a long career in audio then you need to look after your hearing (it's also a good idea wearing ear plugs at gigs and clubs too) 

10

Headphone Output. This output provides an amplified headphone output capable of driving a variety of headphone types

11

Master Level. Use this fader to turn the mix all the way up to 11. Turn it back down a bit if it starts clipping (once it starts clipping, it won't get any louder, it will just sound more distorted)

12


VU Meters. VU stands for Voltage Unit. VU meters give a Root-Mean Square average of a signal (This turns the negative parts of the signal to positive, and then takes an average of the whole signal). VU meters have a relatively slow response time, which means they provide a good indicator of the average signal over a few hundred milliseconds. If the signal is going past 0 dB then this is clipping



How to use
your mixer



System Block Diagram



Further Research

Links to Engineering Channels

Moritz Klein - DIY Modular Synthesis

This YouTube channel has a lot of great explanations on basic principles of electronics, as well as how different modules are made for audio synthesisers and their functions.

The analog oscillator core anyone can build
<https://www.youtube.com/watch?v=QBatvo8bCa4>



3Blue1Brown - Mathematical Principles

This channel is great for learning more generally about mathematics - it covers advanced topics but in a very approachable way

The essence of calculus
<https://www.youtube.com/watch?v=WUvTyaaNkzM>



Coding Train - Software Development

This channel is mostly unrelated audio technology, it refers to a different type of engineering - software engineering. Software is a vital component in all modern digital mixing desks. This channel is a fun way to learn the basics

Coding Challenge #3: The Snake Game
<https://www.youtube.com/watch?v=AaGK-fj-BAM>



Khan Academy - Engineering Courses

If you want to learn more about the practice of electrical engineering (which will also provide a good foundation for analogue and digital electronics), then this is a course which goes over the fundamentals of electrical engineering

<https://www.khanacademy.org/science/electrical-engineering>

